## Message

From: Rumrill, Nancy [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP

(FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=ECC4D19E0739473E8D3B141813288234-NRUMRILL]

**Sent**: 1/31/2019 7:46:12 PM

To: Dan Johnson [Dan Johnson@florencecopper.com]

Subject: RE: Temperature Logging of wells R-07 and R-08

Hi Dan,

Please provide more details on the work over to replace the motors. What equipment will you have to pull from the wells? How it will affect the rest of the operation?

Thanks, Nancy

Nancy Rumrill (<u>rumrill.nancy@epa.gov</u>)
Drinking Water Protection Section (WTR-3-2)
US EPA, Region IX
75 Hawthorne St.
San Francisco, CA 94105
Phone (415) 972-3293

From: Dan Johnson < DanJohnson@florencecopper.com>

**Sent:** Thursday, January 31, 2019 10:22 AM **To:** Rumrill, Nancy <Rumrill.Nancy@epa.gov>

Subject: Temperature Logging of wells R-07 and R-08

Hi Nancy,

Per our earlier discussion, we're experiencing some motor issues in wells R-07 and R-08 and are making arrangements to replace thee motors within the next two days. While these wells are out of service, we would like to conduct temperature logging per the Demonstration of Mechanical Integrity Testing Plan submitted to EPA earlier this month. Please let me know if we could proceed with the proposed temperature logs at your convenience?

Best Regards,

Dan	Johnson	VΡ	•	General Manager	
- Whitelenge works happy. To be applied to a wear work of the field had been a street for the st					

Florence Copper Inc.

1575 W. Hunt Highway Florence AZ USA 85132 C 520-233-1930 T 520-374-3984 F 520-374-3999

E danjohnson@florencecopper.com Web florencecopper.com

"Notice Regarding Transmission

This message is intended only for the person(s) to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is prohibited. Please notify us of the error in communication by telephone (778-373-4533) or by return e-mail and destroy all copies of this communication. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Taseko Mines Limited or any affiliated or associated company. The recipient should check this email and any attachments for the presence of viruses. Neither Taseko Mines Limited nor any affiliated or associated company accepts any liability for any damage caused by any virus transmitted by this email. Thank you "